Inspection Report

By Sri.K. Manjunath
Retd. Executive Engineer

Name of Work: Construction of Anganavadi Bulding Near Maheshwramma temple at Bhuvaneshwarinagara Ward No.14 Bagalagunte, T.Dasarahalli Sub Division.

B.R.No: 698 /17-18 dtd 31/03/2017

Estimate Cost: 12.00 Lakhs

Bill Amount: 1158851.00

Date of Inspection 22-06-2017

Observation and Conclusion:

The above said work "Construction of Anganavadi Building near Maheshwaramma temple at Bhuvaneshwarinagara ward no 14 Bagalagunte, T. Dasarahalli Sub Div." was Given to me by the Concerned ward Engineer.

The above said work is inspected by me along with the Concerned ward Engineer.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿಕೆವಿಕೆ ಅಂಚೆ
ಬೆಂಗಳೂರು

Name of Work: Construction of Anganavadi Bulding Near Maheshwramma temple at Bhuvaneshwarinagara Ward No.14 Bagalagunte, T.Dasarahalli Sub Division.

BR No. 698 , Date. 31/08/2017

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT